

FIG. 1A (PRIOR ART)




FIG. 1B (PRIOR ART)





FIG. 1C (PRIOR ART)






FIG. 3




FIG. 5A



FIG. 5B




FIG. 6




FIG. 7A




FIG. 7B




FIG. 8 (PRIOR ART)

Bristles' freedom of motion

Brushing direction
(parallel to handle axis)

